


Gnatcatcher Circuit Plan



Planned Work:

- New covered conductor has already been installed on nearly all existing overhead portions of the circuit
- Replace an additional 3.53 miles of existing overhead wire with covered conductor at various locations

Expected Improvements:

- **79% reduction** in customer outage time, assuming the same weather conditions in 2020